

P.O. Box 278  
316 Franklin Street  
Linesville, PA 16424  
Web Site: [www.bairs.com](http://www.bairs.com)

Yogi - Owner  
Brian Bair - Parts


# YOGI BAIRS<sup>9</sup> INC.

**Parts & Services for Corvettes**



Order Line **800-421-9644**  
Information **814-683-4223**  
24 Hour FAX **814-683-5200**  
E-Mail **[sales@bairs.com](mailto:sales@bairs.com)**

## HOW TO CORRECT POWER STEERING PUMP VALVE FAILURE



### Instructions:

1. Remove pressure house.
2. Remove fitting (#24).
3. Remove flow control valve (#9).
4. Polish valve.
5. Clean pump valve area.
6. Reassemble.